Printed on: 12/25/2008 5:45:58 AM

PRELIMINARY REPORT  OC  ANTATION			NTSB ID: DCA09RA007				Most Critical Injury:		
			Occurrence Date: 11/04/2008				Investigated By: Foreign		
			Occur	Occurrence Type: Accident					
Location/Time									
Nearest City/Place		State		Zip Code	Local Time		Time Zone		
Mexico City					1846		CST		
Aircraft Information									
Registration Number	Aircraft Manufacturer					Model/Series Number			
XC-VMC									
Type of Aircraft: Airplane				Amateur Built Aircraft?					
Injury Summary:	Fatal	14	Serious Mi		Minor	nor		None	
Revenue Sightseeing Flight:				Air Medical Transport Flight:					

## Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On November 4, 2008, at 1846 central standard time, a Learjet model 45, registration XC-VMC, impacted terrain and buildings while on approach to Benito Jurez Mexico City International Airport (MMMX), Mexico City, Mexico. The 9 passengers and crew onboard the airplane were killed and the airplane was destroyed. Initial reports indicated that fourteen people on the ground were killed and an additional 40 people on the ground were injured. The airplane was registered to Secretairia du Gobernacion of Mexico, and operated by Centro de Servicios Cooperatives Aeros. The flight originated from the Ponciano Arriaga International (MMSP) airport, San Luis Potosi, Mexico. Visual meteorological conditions prevailed at the time of the accident.

The investigation is being conducted by the Mexican Directin General de Aeronutica Civil (DGAC). The NTSB has assigned an Accredited Representative to assist the investigation under the provisions of ICAO Annex 13 as the Country of Manufacture and Design of the airplane and engines.

TRANSO_
National Transportation Safety Board
0 7
PRELIMINARY REPORT
7 *** >
AYIATION

NTSB ID: DCA09RA007

PRELIMINARY REPORT AVIATION		Occurrence Date: 11/04/2008									
		Occurrence Type: Accident					]				
Other Aircraft Involved							•				
Registration Number	Aircraft Manufacture	Aircraft Manufacturer					Model/Series Number				
Accident Information							•				
					Occurred Durin	ng:					
_			•								
Crew	ew Name					Certificate No.			Injury		
Pilot	ot										
2											
3											
4											
5											
6											
Operator Information											
Name Operator Des					gnator Code Doing Business As						
Street Address City				ty		•		Zip Code			
-Type of Certificate(s) Held: None											
Air Carrier Operating Certifica	:e(s):										
Operating Certificate:					Operator Certificate:						
Regulation Flight Conducted Under: Unknown											
Type of Flight Operations Cond	ucted:										
Flight Plan/Itinerary											
Type of Flight Plan Filed:											
Last Departure Point					State	Airport	Identifier				
Destination					State	Airport	Identifier				
Weather Information					•						
Investigator's Source:					lity ID:		Observation Time (Local):				
Sky/Lowest Cloud Condition:		Ft. AGL				AGL					
Lowest Ceiling:		Ft. AGL Visibility: SM Altimeter:						"Hg			
PRELIMINARY INFORMATION - SUBJECT TO CHANGE											

## National Transportation Safety Board PRELIMINARY REPORT

NTSB ID: DCA09RA007

PRELIMINARY RÉPORT			currence Date: 11/04/2008				
AVÎATIQN		Occurrence Type: Accident					
Weather Information	(Continued from page 2)						
Temperature: °C	Dew Point:	°C	Wind Direction:				
Wind Speed: Kts	. Gusts: K	ts.	Weather Conditions at Accident S	ite:			
Administration Data							
Notification From				Date			
DGAC							
FAA District Office/Coordinator			Investigator-In-Charge (I Joseph M. Sedor	IC)			